



Ashust user Juno o Ashust user Juno o Shree Ram Enterprise

Ahmedabad



Material Handling Equipment







Material Handling Equipment









WEBBING SLING & CARGO LASHING







Material : 100% high tensile polyester (PES) Single ply or double ply

The working load can be distinguiguished easily by the colour and the width It is colour coded according to DIN-EN1492-1, also it has capacity stripes on

The sling (each stripe is equal to 1 ton capacity).

It can offer Wide and smooth load surface to the lifted object.

It has high protection against the abrasion and damage.

To avoid being damaged by the sharp objects, it can also be used together withe proper protective sleeve.

Safety factor: 4:1,5:1,6:1,7:1,8:1 is available. Temperature:-40 C to 100 C

Manufactured according to EC directive 2006/42/EC



webbing width (mm)	Colour coded according to DIN-EN-1492-1	Working load limit with 1 webbing sling					Working Limit with 2 webbing sling			
		Straoght lift	Choked lift	Lift in different angle			Straight lift	Choked lift	Straight lift	Choked lift
				0° - 7°	7°- 45°	45°- 60°	45°	45°	45°- 60°	45°- 60°
			6	U	Δ	Δ	Δ	50	\triangle	50
		1	0.8	2	1.4	1	1.4	1.12	1	0.8
25/30	WLL1T	1000	800	2000	1400	1000	1400	1120	1000	800
50/60	WLL2T	2000	1600	4000	2800	2000	2800	2240	2000	1600
75/90	WLL3T	3000	2400	6000	4200	3000	4200	3360	3000	2400
100/120	WLL4T	4000	3200	8000	5600	4000	5600	4480	4000	3200
125/140	WLL5T	5000	4000	10000	7000	5000	7000	5600	5000	4000
150	WLL6T	6000	4800	12000	8400	6000	8400	6720	6000	4800
200	WLL8T	8000	6400	16000	11200	8000	11200	8960	8000	6400
250	WLL10T	10000	8000	20000	14000	10000	14000	11200	10000	8000
300	WLL12T	12000	9600	24000	16800	12000	16800	13440	12000	9600

Do not exceed working load limit

Prevent shock-loading.

Where selecting a sling it is very important to consider the angles at Which the sling will be used.

slings are subject to cutting when lifting items with sharp edges. In this case always use wear sleeves. do not use a damaged sling.

Never make knots in a sling.

Never drag a sling from underneath a load that is resting on it.

Chemical active environments can affect the strength of slings.

Inspect slings weekly or more frequently depending on sling use.

Always store slings in a cool dry and dark place when they-are not in use for prolonged periods.

always read and understand the operating instruction before use.

Shree Ram Enterprise

Manufacturers & Exporters Of Material Handling Equipments

57, Mahadev Estate, Part-3, Nr. Ramol Police Station, Ramol, Ahmedabad -382449 Gujarat

M. 9924438690, 9712051056, 8488063119

sre5700@gmail.com

www.shreeramenterprise.in